



EXAMPLE

Typical Reports issued under the Detec Monitoring Services and Maintenance Option showing a typical 'moisture event'.

1. In April, Remote Monitoring Unit #8535 reported excessive moisture accumulation in zone #3. (shown in red)

2. In this example, water from a blocked roof drain downspout was wicking up the sheathing behind the exterior cladding, *although no visible clues indicated a problem.*



3. Over the next few weeks the problem was corrected, and by June the sheathing moisture content was drying to acceptable levels (shown in yellow)

